

NEW MEMORY DEVICES		

NEW MICROCONTROLLER DEVICES		

NEW PROGRAMMABLE LOGIC DEVICES		

IMPROVMENTS:

- (MTI) MT28F800B5B TSOP-48 ON FLASHTOP S271: PROGRAMMING ERROR FIXED
- (STM) STM32LXXX: OPTION BYTE SUPPORT FIXED